

Part 2 – Investigating FOD Damage


Event #3

Fan Blade Failure on Takeoff

Fan Blade Failure on Takeoff

- Flight crew heard loud bang and noticed vibration on #2 engine during takeoff roll
- Takeoff was aborted
- While taxiing off the runway and back to gate, another aircraft reported seeing smoke and flames coming from the #2 engine (aft fuselage mounted)
- Engine was shut down

Numerous Fan Blades Are Broken



LE of Inlet Struts Shown



TE of Inlet Strut



1st Stage Fan Rotor

