

# Part 2 – Investigating FOD Damage


Event #3

Fan Blade Failure on Takeoff

# Fan Blade Failure on Takeoff

- Flight crew heard loud bang and noticed vibration on #2 engine during takeoff roll
- Takeoff was aborted
- While taxiing off the runway and back to gate, another aircraft reported seeing smoke and flames coming from the #2 engine (aft fuselage mounted)
- Engine was shut down

# Numerous Fan Blades Are Broken



# LE of Inlet Struts Shown



# TE of Inlet Strut



# 1<sup>st</sup> Stage Fan Rotor

