


Part 2 Investigating FOD Damage

Event #4

HPC-10 Blade Failure

Event #4 HPC-10 Blade Failure

- Loud bang during flight
- Engine shut down
- HPC-10 blade found broken



Damage AFT of HPC-10 Heavy



Light Damage HPC-1 thru HPC-9

